

**Distributed: April 9, 2021**

## Boil Water Advisory Lifted for Indian Hills, MO6036052 – Section B, Lakeside Drive

On Thursday April 8, 2021 Indian Hills UOC issued a precautionary boil water advisory for customers on Lakeside Drive (Section B) of the Indian Hills subdivision.

Bacteriological samples collected in the affected area indicate that there is no contamination in the drinking water. As such, the precautionary boil water advisory is being lifted on Friday April 9, 2021.

Customers are advised to flush all the water lines in their residence for five (5) minutes by operating all water faucets (both hot and cold) and flushing toilets. Discard three (3) batches of ice cubes and disinfect the ice bin prior to use. Hot water heaters, water coolers, in-line filters, etc. should be flushed to completely replace at least one full volume of the appliance. Disinfect and/or replace all filters on units, and run water softeners through a regeneration cycle prior to use. Consult your owner's manual for additional flushing/cleaning/disinfecting directions.

Please share this information with others who drink the water and may not have directly received this notification.

Any customer who notices colored or odorous water or has any questions concerning this notification should contact Indian Hills UOC customer experience at 1-866-747-0493 or [support@indianhillsuoc.com](mailto:support@indianhillsuoc.com).